

Foreward

ASBESTOS SURVEY REPORT FOR HARRATON AND DISTRICT COMMUNITY ASSOCIATION, BONEMILL LANE, WASHINGTON, NE38 8BQ.

I have enclosed for your information and retention the most recent asbestos survey (Management) which applies to the property stated above. The purpose of the survey is to identify as far as possible, the materials containing asbestos fibres in your property.

The attached report is divided in sections so as to give as much information as possible, a basic reference section for use by premises managers and a more detailed report for use by contractors on site etc.

Plan of the Building and Sample Locations

This contains a plan of the building and identifies where asbestos samples have been taken from.

Photographs of Areas Sampled

This section contains photographs of all the areas where samples were taken. These photographs can be used when carrying out the periodic inspections to see if there has been any change or deterioration in its condition.

Survey Information

This section contains the survey information as printed from the central database held at Land and Property. It describes the type of asbestos present, its location, condition etc. Contractors should be shown this section along with the others when they are shown the register prior to starting any work.

Priority Risk Assessments

This section contains assessments which have been created using information from the survey and information on your property. This assessment helps to determine how often periodic checks on any asbestos need to be carried out by your Samo.

5 Simple Steps to Asbestos Management

This section details procedures for managing asbestos in your property. It gives guidance on the register, the inspections, any planned work and what to do when contractors arrive on site.

Commonly asked Questions

This section covers questions most commonly asked and can be referred to as/when the need arises.

The building has been surveyed as comprehensively as possible, all potentially fibrous materials have been examined and where necessary analysed by competent UKAS accredited analysts and the findings of both recorded in the report.

This report is an important document and must be referred to before any building works are carried out. The report must be kept with your handbook and the checklists completed on a regular basis. You will be reminded when your specific checklists are due for submission.

Information for Employees Working in Premises where Asbestos Containing Materials Exist.

Asbestos is made up of fibrous materials, which are flexible, mechanically strong and resistant to stretching, heat and chemicals. As a consequence asbestos has been used extensively in buildings. Examples of asbestos containing materials found in buildings include exterior asbestos cement cladding; gutters and pipes; fireproof sprays on structural steel joists; insulation boards in service ducts and wall partitions; ceiling and floor tiles and pipe and boiler lagging.

Asbestos containing products can produce very small fibrous dust particles, which can not be seen by the naked eye. It is only when these fibres become airborne, due to damage, deterioration, disturbance etc, that there is a risk to health.

If asbestos is maintained in good condition and is not disturbed or damaged it does not pose a health risk.

The authority has a management system for ensuring that you are not exposed to asbestos containing materials that are in poor condition and may pose a health risk. This system is based on sound principals laid down by legislation and associated codes of practice and guidance.

It is not appropriate simply to remove all asbestos containing materials in buildings. Asbestos materials that are sound, undamaged and not releasing dust should be left alone. Any disturbance to such materials, however carefully controlled, will release fibres and be counter-productive.

Within the building you occupy, your department has nominated a Site Asbestos Monitoring Officer (SAMO). This individual is responsible for inspecting the asbestos containing materials to ensure they are not in a dangerous condition. Should you have any concerns about suspect materials within your premises you should contact the SAMO.

Restrictions on use, distribution and publication of the report

We accept no responsibility or liability for the consequences of this document being used for purpose other than for which it was commissioned.

To the extent that the document is based on the information available at the time of writing, Sunderland City Council accepts no liability for any consequences should this report be used for any other purpose

If you require any further information regarding the report or its application please contact Caroline Bage, Asbestos Manager on Tel: 07557 938966.

Yours sincerely,

Neil Guthrie
Director of Development and Property

Sunderland
City Council

Sunderland City Council

Control of Asbestos Regulations 2012

Asbestos Register for

Harraton and District CA, Bonemill Lane, Washington



UPRN: -374621

TF Ref:

Location of register:-

Premises Manager / Samo: - Tenant

Date: 23 April 2025

Contact Numbers List: -

Caroline Bage Asbestos Manager – 07557 938966

Contents

| | <u>Section</u> |
|---|----------------|
| • Plan of building and sample locations | 1 |
| • Photographs of areas sampled | 2 |
| • Survey information | 3 |
| • Asbestos Management Plan, Priority Assessments, | 4 |
| • Contacts Form, Code of Practice | 4 |
| • 5 Simple Steps of Asbestos Management | 5 |
| • Commonly asked questions | 6 |

Appendices

| | |
|---|----|
| • Form 1 – Visitor Register | 7 |
| • Form 2 – Periodic Return Checklist and Schedule | 8 |
| • Form 3 – Works Notification Form | 9 |
| • Form 4 – Registration of All Disturbances | 10 |
| • Form 5 – Training Records | 11 |

Plan of Building and Samples Location

- (Item 1) Ref: 374621-16 – Pipe lagging (Plant Room/Rm 001) – No Risk
- (Item 2) Ref: 374621-17 – Pipework flange gasket (Plant Room/Rm 001) - Low Risk
- (Item 3) Ref: 374621-18 – Gasket to boiler (Plant Room/Rm 001) – No Risk
- (Item 4) Ref: 374621-19 – Debris to walls (Plant Room/Rm 001) – No Risk
- (Item 5) Ref: 374621-20 – Seal to metal boiler flue (Plant Room/Rm 001) – No Risk
- (Item 6) Ref: 374621-1 – Floor covering (Store/Rm 003) – No Risk
- (Item 7) Ref: As 374621-1 – Floor covering (Store/Rm 003a) – No Risk
- (Item 8) Ref: As 374621-1 – Floor covering (Stage/Rm 008a) – No Risk
- (Item 9) Ref: 374621-15 – To fibreboard ceiling (Boiler Cupboard/Rm 009a) – Very Low Risk
- (Item 10) Ref: 374621-11 – Sink pad (Bar/Rm 010) – Very Low Risk
- (Item 11) Ref: As 374621-14 – Textured coating to ceiling (Lounge/Rm 012) – Very Low Risk
- (Item 12) Ref: 374621-12 – Floor covering under seating (Lounge/Rm 012) – Very Low Risk
- (Item 13) Ref: 374621-13 – Bitumen adhesive (Lounge/Rm 012) – Very Low Risk
- (Item 14) Ref: 374621-14 – Textured coating to ceiling (Store/Rm 012a) – Very Low Risk
- (Item 15) Ref: As 374621-13 – Bitumen adhesive (Store/Rm 012a) – Very Low Risk
- (Item 16) Ref: 374621-6 – Panel around door to 0/020 (Common Room/Rm 016) – Very Low Risk
- (Item 17) Ref: 374621-5 – Floor covering (Store/Rm 016a) – No Risk
- (Item 18) Ref: 374621-7 – Ceiling (Common Room Lobby/Rm 017) – Very Low Risk
- (Item 19) Ref: 374621-8 – Floor covering (Common Room Lobby/Rm 017) - No Risk
- (Item 20) Ref: 374621-10 – Ceiling (WC/Rm 018) – No Risk
- (Item 21) Ref: As 374621-8 – Floor covering (WC/Rm 018) – No Risk
- (Item 22) Ref: 374621-9 – Ceiling (WC Lobby/Rm 018a) – Very Low Risk
- (Item 23) Ref: As 374621-8 – Floor covering (WC/Rm 018a) – No Risk
- (Item 24) Ref: As 374621-10 – Ceiling (WC/Rm 019) – No Risk
- (Item 25) Ref: As 374621-8 – Floor covering (WC/Rm 019) – No Risk
- (Item 26) Ref: As 374621-9 – Ceiling (WC Lobby/Rm 019a) - Very Low Risk
- (Item 27) Ref: As 374621-8 – Floor covering (WC Lobby/Rm 019a) – No Risk
- (Item 28) Ref: As 374621-3 – Floor covering (Store/Rm 020) – No Risk
- (Item 29) Ref: As 374621-3 – Floor covering (Lobby/Rm 022) – No Risk
- (Item 30) Ref: As 374621-3 – Floor covering (Stairwell Lobby/Rm 023) – No Risk
- (Item 31) Ref: As 374621-4 – Stair nosing (Stairwell Lobby/Rm 023) – Very Low Risk
- (Item 32) Ref: 374621-2 – Adhesive to floor (Store/Rm 025) – Very Low Risk
- (Item 33) Ref: 374621-3 - Floor covering (Landing/Rm 1/01) No Risk
- (Item 34) Ref: 374621-4 – Stair nosing (Landing/Rm 1/01) – Very Low Risk
- (Item 35) Ref: As 374621-3 – Floor covering (Lounge/Rm 1/02) – No Risk
- (Item 36) Ref: As 374621-3 – Floor covering (Toilet/Rm 1/03) – No Risk
- (Item 37) Ref: As 374621-3 – Floor covering (Hall/Rm 1/04) – No Risk
- (Item 38) Ref: 37421-21 – Damp proof course (External) – No Risk
- (Item 39) Ref: 374621-22 – Sealant around window frames (External) – Very Low Risk

- (Item 40) Ref: 22-55274-10 – Ceiling (Main Hall & Stage / Area 8) – No Risk
- (Item 41) Ref: 22-55274-10 – Ceiling (Multi Use Room / Area 28) – No Risk
- (Item 42) Ref: 22-55274-11 – Floor forming ceiling below (Loft 008 and 1004 / Area 31) – No Risk
- (Item 43) Ref: 22-55274-3 – Loose paint to walls (Boiler Room / Area 32) – No Risk
- (Item 44) Ref: 22-55274-5 – Rope gasket to pipe inlet (Boiler Room / Area 32) – Low Risk
- (Item 45) Ref: 22-55274-6 – Coating to boiler Vessels (Boiler Room / Area 32) – No Risk
- (Item 46) Ref: 22-55274-7 – Cork gasket seal to front plate (Boiler Room / Area 32) – No Risk
- (Item 47) Ref: 22-55274-8 – Seal to top of plate (Boiler Room / Area 32) – No Risk
- (Item 48) Ref: 22-55274-9 – Rope gasket to front plate (Boiler Room / Area 32) – Low Risk

Please note the survey carried out was non-intrusive and any areas not listed above may not have been accessed or had samples taken, should major refurbishment be planned for the property, further investigation will be required.

Photographs of Areas Sampled



Item 1 Ref: 374621-16

The pipe lagging in the plant room (Rm 0/01) does not contain asbestos.



Item 2 Ref: 374621-17

The pipework flange gasket in the plant room (Rm 0/01) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 3 Ref: 374621-18

The gasket to the boiler in the plant room (Rm 0/01) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 4 Ref: 374621-19

The debris to walls in the plant room (Rm 0/01) does not contain asbestos.



Item 5 Ref: 374621-20

The seal to metal boiler flue in the plant room (Rm 0/01) does not contain asbestos.



Item 6 Ref: 374621-1

The floor covering in the store (Rm 0/03) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 7 Ref: As 374621-1

The floor covering in the Store (Rm 0/03a) does not contain asbestos.



Item 8 Ref: As 374621-1

The floor covering the stage (Rm 0/08a) does not contain asbestos.



Item 9 Ref: 374621-15

The textured coating to the fibreboard ceiling in the boiler cupboard (Rm 0/09a) does contain asbestos.

Any change in appearance should be reported to Property Services.

Photographs of Areas Sampled (Cont)



Item 10 Ref: 374621-11

The sink pad in the bar (Rm 0/10) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 11 Ref: As 374621-14

The textured coating behind the plaster skim in the lounge (Rm 0/12) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 12 Ref: 374621-12

The floor covering under the seating in the lounge (Rm 0/12) does contain asbestos.

Any change in appearance should be reported to Property Services.

Photographs of Areas Sampled (Cont)



Item 13 Ref: 374621-13

The bitumen to concrete floor under blue modern flooring in the lounge (Rm 0/12) does contain asbestos.


Any change in appearance should be reported to Property Services.



Item 14 Ref: 374621-14

The textured coating to the plasterboard ceiling in the store (Rm 0/12a) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 15 Ref: As 374621-13

The bitumen to concrete floor under blue modern flooring in the store (Rm 0/12a) does contain asbestos.

Any change in appearance should be reported to Property Services.

Photographs of Areas Sampled (Cont)



Item 16 Ref: 374621-6

The panels around door to 0/020 in the common room (Rm 0/16) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 17 Ref: 374621-5

The floor covering in the store (Rm 0/16a) does not contain asbestos.



Item 18 Ref: As 374621-13

The textured coating onto plasterboard ceiling in the common room lobby (Rm 0/17) does contain asbestos.

Any change in appearance should be reported to Property Services.

Photographs of Areas Sampled (Cont)



Item 19 Ref: 374621-8

The floor covering in the common room lobby (Rm 0/17) does not contain asbestos.



Item 20 Ref: 374621-10

The ceiling in the WC (Rm 0/18) does not contain asbestos.



Item 21 Ref: As 374621-8

The floor covering in the WC (Rm 0/18) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 22 Ref: 374621-9

The ceiling in the WC lobby (Rm 0/18a) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 23 Ref: As 374621-8

The floor covering in the WC lobby (Rm 0/18a) does not contain asbestos.



Item 24 Ref: As 374621-10

The ceiling in the WC (Rm 0/19) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 25 Ref: As 374621-8

The floor covering in the WC lobby (Rm 0/19) does not contain asbestos.



Item 26 Ref: As 374621-9

The ceiling in the WC lobby (Rm 0/19a) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 27 Ref: As 374621-8

The floor covering in the WC lobby (Rm 0/19a) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 28 Ref: As 374621-3

The floor covering in the Store (Rm 0/20) does not contain asbestos.



Item 29 Ref: As 374621-3

The floor covering in the lobby (Rm 0/22) does not contain asbestos.



Item 30 Ref: As 374621-3

The floor covering in the Stairwell lobby (Rm 0/23) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 31 Ref: As 374621-4

The stair nosing in the stairwell lobby (Rm 0/23) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 32 Ref: 374621-2

The adhesive to floor in the Store (Rm 0/25) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 33 Ref: As 374621-3

The floor covering in the landing (Rm 1/01) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 34 Ref: As 374621-4

The stair nosing in the landing (Rm 1/01) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 35 Ref: As 374621-3

The floor covering in the lounge (Rm 1/02) does not contain asbestos.



Item 36 Ref: As 374621-3

The floor covering in the toilet (Rm 1/03) does not contain asbestos.

Photographs of Areas Sampled (Cont)

NO PHOTOGRAPH
PROVIDED

Item 37 Ref: As 374621-3

The floor covering in the hall
(Rm 1/04) does not contain
asbestos.



Item 38 Ref: 374621-21

The damp proof course
(Externally) does not contain
asbestos.



Item 39 Ref: As 374621-22

The sealant around window
frames (Externally) contains
asbestos.

Any change in appearance
should be reported to Property
Services.

Photographs of Areas Sampled (Cont)



Item 40 Ref: 22-55274-10

The ceiling in the Main Hall and Stage (Area 8) does not contain asbestos.



Item 41 Ref: 22-55274-10

The ceiling in the Multi use Room (Area 28) does not contain asbestos.



Item 42 Ref: 22-55274-11

The floor forming ceiling below in the loft – 008 and 1-004 (Area 31) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 43 Ref: 22-55274-3

The loose paint to walls in the Boiler Room (Area 32) does not contain asbestos.



Item 44 Ref: 22-55274-5

The rope gasket to pipe inlet in the Boiler Room (Area 32) does contain asbestos.

Any change in appearance should be reported to Property Services.



Item 45 Ref: 22-55274-6

The vessels- coating to boiler in the Boiler Room (Area 32) does not contain asbestos.

Photographs of Areas Sampled (Cont)



Item 46 Ref: 22-55274-7

The vessels – cork gasket seal to front plate in the Boiler Room (Area 32) does not contain asbestos.



Item 47 Ref: 22-55274-8

The vessels – seal to top of plate in the Boiler Room (Area 32) does not contain asbestos.



Item 48 Ref: 22-55274-9

The rope gasket to front plate to boiler in the Boiler Room (Area 32) does contain asbestos.

Any change in appearance should be reported to Property Services.

Five Simple Steps to Asbestos Management

Each property has a nominated site asbestos monitoring officer (SAMO). The SAMO is responsible for maintaining this register and ensuring all necessary personnel are aware of the register including all maintenance, construction and service installers; undertaking periodic inspections and liaising with the Departmental Asbestos Co-ordinator and the Asbestos Manager in Property Services as necessary.

The SAMO's role is very important but this guide is hoped to ensure the requirements are easy and simple to follow.

Step 1 – Receiving the Register

The SAMO is the tenant.

And the person is responsible for the register, where it is located and that it is kept up to date.

The register contains a plan of the premises and a photographic schedule of where the asbestos is and what risk is associated.

The SAMO must make all employees aware of the locations and should let any contractors entering the building view the register before any work is started.

Step 2 – Periodic Inspections

The SAMO must look at the locations photographed and compare the asbestos now to when the photograph was taken and complete the checklist attached (Form 2).

The checklists are to be completed periodically in accordance with the schedule attached.

Should the SAMO come across some asbestos which has been disturbed, whether during refurbishment works or during the normal course of wear and tear, they should complete Form 4 as far as possible and contact Property Services for advice and remedial action.

In the meantime, they should ensure that access to the area containing the disturbed or damaged asbestos is prohibited until Property Services has made recommendations.

Step 3 – Planned Work

All planned works that may disturb or danger any asbestos indicated, should be reported to Property Services using form 3 at least 21 days before the work is due to commence.

Step 4 – Contractors on Site

If a contractor arrives on site, the SAMO must :

- a. Make sure they read/view the register
- b. Get contractor to sign register to say he has read it (Form1).
- c. Get confirmation from the contractor that proposed works will not disturb any asbestos areas.
- d. If area is disturbed that was not identified in Register, advise Property Services immediately and complete Form 4.

Step 5 – Monitoring the Register

On completion of work get contractor to sign to say they didn't disturb any areas.

If alterations have occurred details should be forwarded to Property Services.

If you, as SAMO, are to leave your post, please notify your Departmental Co-ordinator to appoint another person and notify Property Services and the front of your register.

In the event of an exposure of asbestos, please refer to your site specific emergency procedures. However, as a minimum:

- Seal the area off completely. (Lock the area off if possible and post a notice on the door, "No access - Contact ")
- If there is any air movement systems within the premises, shut it off.
- Contact the Asbestos Manager on 07557938966 immediately. Who will arrange for any remedial works / air monitoring.
- Start to complete the "Registration of Disturbances" form, which is in your register (Section 10 in the new style register).

Once the remedial works have been carried out and a clear air test certificate has been issued. Access to the area can be re-opened.

In the event that you are unable to contact the Asbestos Manager, please contact the Civic Centre on 520 5555 and ask for assistance from a building surveyor. Out of hours ring the City Alarm and Emergency Control room on 553 1999.

Central Safety can be contacted on 561 2311.

In the event of a fire (or drill), the asbestos register must be taken outside to show the emergency services.

Commonly Asked Questions.

- **How often should SAMO's undertake inspections of asbestos containing materials?**
The Asbestos Manager will inform the SAMO of how often the inspections should be undertaken.
- **What should a SAMO do if the asbestos containing materials are disturbed or damaged?**
The SAMO should prohibit access to the areas until the Asbestos Manager in Property Services has been contacted and given recommendations.
- **Can employees put up decorations onto asbestos containing materials?**
No decorations should be attached to asbestos containing materials. However, it is understood that some decoration is already attached to asbestos containing materials and these should be left in place.
- **Can a room with asbestos containing materials in the ceiling and wall be painted?**
Yes, as long as the material is not rubbed or sanded down, as this may result in the release of asbestos fibres.
- **Why isn't all asbestos containing materials removed from buildings?**
Because it is safer to leave asbestos containing materials in good condition in buildings. Removing the materials will result in a greater risk to health because of the consequential release of fibres.
- **When will asbestos containing material be removed from my building?**
Asbestos containing materials will be removed if work involves the disturbance of the material e.g. during the refurbishment or dismantling of part of the building or structure.
- **What should a SAMO do if he/she has had no training in use of the register?**
The SAMO should ring the Departmental Co-ordinator who will arrange training.

Form 2Inspection Schedule

| Picture | Location | Risk | Inspection Frequency | Date of return |
|----------------|--|----------------------|----------------------|-----------------|
| <i>Item 1</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 2</i> | <i>Pipework flange gasket (Plant Room/Rm 001)</i> | <i>Low Risk</i> | <i>6 monthly</i> | <i>9.8.2025</i> |
| <i>Item 3</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 4</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 5</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 6</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 7</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 8</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 9</i> | <i>To fibreboard ceiling (Boiler Cupboard/Rm 009a)</i> | <i>Very Low Risk</i> | <i>12 monthly</i> | <i>9.2.2026</i> |
| <i>Item 10</i> | <i>Sink pad (Bar/Rm 010)</i> | <i>Very Low Risk</i> | <i>12 monthly</i> | <i>9.2.2026</i> |
| <i>Item 11</i> | <i>Textured coating to ceiling (Lounge/Rm 012)</i> | <i>Very Low Risk</i> | <i>12 monthly</i> | <i>9.2.2026</i> |
| <i>Item12</i> | <i>Floor covering under seating (Lounge/Rm 012)</i> | <i>Very Low Risk</i> | <i>12 monthly</i> | <i>9.2.2026</i> |
| <i>Item13</i> | <i>Bitumen adhesive (Lounge/Rm 012)</i> | <i>Very Low Risk</i> | <i>12 monthly</i> | <i>9.2.2026</i> |
| <i>Item14</i> | <i>Textured coating to ceiling (Store/Rm 012a)</i> | <i>Very Low Risk</i> | <i>12 monthly</i> | <i>9.2.2026</i> |
| <i>Item 15</i> | <i>Bitumen adhesive (Store/Rm 012a)</i> | <i>Very Low Risk</i> | <i>12 monthly</i> | <i>9.2.2026</i> |
| <i>Item 16</i> | <i>Panel around door to 0/020 (Common</i> | <i>Very Low Risk</i> | <i>12 monthly</i> | <i>9.2.2026</i> |

| | | | | |
|----------------|--|--------------------------|-------------------|-----------------|
| | Room/Rm 016) | | | |
| Item 17 | No asbestos | Is present | | |
| Item 18 | Ceiling (Common Room Lobby/Rm 017) | Very Low Risk | 12 monthly | 9.2.2026 |
| Item 19 | No asbestos | Is present | | |
| Item 20 | No asbestos | Is present | | |
| Item 21 | No asbestos | Is present | | |
| Item 22 | Ceiling (WC Lobby/Rm 018a) | Very Low Risk | 12 monthly | 9.2.2026 |
| Item 23 | No asbestos | Is present | | |
| Item 24 | No asbestos | Is present | | |
| Item 25 | No asbestos | Is present | | |
| Item 26 | Ceiling (WC Lobby/Rm 019a) | Very Low Risk | 12 monthly | 9.2.2026 |
| Item 27 | No asbestos | Is present | | |
| Item 28 | No asbestos | Is present | | |
| Item 29 | No asbestos | Is present | | |
| Item 30 | No asbestos | Is present | | |
| Item 31 | Stair nosing (Stairwell Lobby/Rm 023) | Very Low Risk | 12 monthly | 9.2.2026 |
| Item 32 | Adhesive to floor (Store/Rm 025) | Very Low Risk | 12 monthly | 9.2.2026 |
| Item 33 | No asbestos | Is present | | |
| Item 34 | Stair nosing (Landing/Rm 1/01) | Very Low Risk | 12 monthly | 9.2.2026 |
| Item 35 | No asbestos | Is present | | |
| Item 36 | No asbestos | Is present | | |
| Item 37 | No asbestos | Is present | | |
| Item 38 | No asbestos | Is present | | |
| Item 39 | Sealant around window frames (External) | Very Low Risk | 12 monthly | 9.2.2026 |
| Item 40 | No asbestos | Is present | | |
| Item 41 | No asbestos | Is present | | |
| Item 42 | No asbestos | Is present | | |
| Item 43 | No asbestos | Is present | | |

| | | | | |
|----------------|---|--------------------------|------------------|-----------------|
| <i>Item 44</i> | <i>Rope Gasket to Pipe Inlet (Boiler Rm/Area 32)</i> | <i>Very Low Risk</i> | <i>6 monthly</i> | <i>9.8.2025</i> |
| <i>Item 45</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 46</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 47</i> | <i>No asbestos</i> | <i>Is present</i> | | |
| <i>Item 48</i> | <i>Rope Gasket to Front Plate (Boiler Rm/Area 32)</i> | <i>Very Low Risk</i> | <i>6 monthly</i> | <i>9.8.2025</i> |
| | | | | |
| | | | | |
| | | | | |

Form 2**Periodic Return**

| | |
|----------------------------------|--|
| School/Site | |
| Date of Inspection | |
| Inspection By (signature) | |
| Print Name | |

Good Practice Guidance:

- Take photographs of ACMs for each inspection and store for future reference
- Compare previous photographs with current condition state to determine whether there has been any deterioration since the last inspection
- Replace missing/damaged asbestos labels/stickers

| | | | |
|-------------|------------------|------------------------|-----------------|
| <u>Ref:</u> | <u>Condition</u> | <u>Action Required</u> | <u>Comments</u> |
| | Same/change | Yes/No | |

Sunderland
City Council

For Office Use Only

| | |
|--------------------------------|--|
| Actions Required | |
| Actions Completed | |
| Alterations to Register | |