

**Form 2**Inspection Schedule

Picture	Location	Risk	Inspection Frequency	Date of return
Item 1	No asbestos	Is present		
Item 2	No asbestos	Is present		
Item 3	No asbestos	Is present		
Item 4	No asbestos	Is present		
Item 5	No asbestos	Is present		
Item 6	No asbestos	Is present		
<b>Item 7</b>	<b>Paper lined fibreboard ceiling – Ground floor (Room 2)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 8	No asbestos	Is present		
Item 9	No asbestos	Is present		
Item 10	No asbestos	Is present		
<b>Item 11</b>	<b>Paper lined fibreboard ceiling – Ground floor (Room 3)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 12	No asbestos	Is present		
Item 13	No asbestos	Is present		
Item 14	No asbestos	Is present		
<b>Item 15</b>	<b>Paper lined fibreboard ceiling – Ground floor (Room 4)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 16	No asbestos	Is present		
Item 17	No asbestos	Is present		
<b>Item 18</b>	<b>Paper lined fibreboard ceiling – Ground floor (Room 5)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 19	No asbestos	Is present		
Item 20	No asbestos	Is present		
Item 21	No asbestos	Is present		
Item 22	No asbestos	Is present		

<i>Item 23</i>	<i>Paper lined fibreboard ceiling – Ground floor (Room 7)</i>	<i>Low</i>	<i>6 monthly</i>	<i>03.04.26</i>
Item 24	No asbestos	Is present		
<i>Item 25</i>	<i>Paper lined fibreboard ceiling – Ground floor (Room 8)</i>	<i>Low</i>	<i>6 monthly</i>	<i>03.04.26</i>
Item 26	No asbestos	Is present		
<i>Item 27</i>	<i>Ceiling panels above suspended ceiling – Ground Floor (Room 9)</i>	<i>Low</i>	<i>6 monthly</i>	<i>Do not Inspect</i>
<i>Item 28</i>	<i>Ceiling panels above suspended ceiling – Ground Floor (Room 10)</i>	<i>Low</i>	<i>6 monthly</i>	<i>Do not Inspect</i>
<i>Item 29</i>	<i>Redundant Flue pipe within ceiling void – Ground Floor (Room 10)</i>	<i>Very Low</i>	<i>12 monthly</i>	<i>03.04.26</i>
<i>Item 30</i>	<i>Paper lined fibreboard ceiling – Ground floor (Room 11)</i>	<i>Low</i>	<i>6 monthly</i>	<i>03.04.26</i>
Item 31	No asbestos	Is present		
<i>Item 32</i>	<i>Paper lined fibreboard ceiling – Ground floor (Room 12)</i>	<i>Low</i>	<i>Do not Inspect</i>	<i>Removal required before access</i>
<i>Item 33</i>	<i>Board debris to suspended ceiling tops – Ground Floor (Room 12)</i>	<i>Medium</i>	<i>Do not Inspect</i>	<i>Removal required before access</i>
Item 34	No asbestos	Is present		

Item 35	No asbestos	Is present		
<b>Item 36</b>	<b>Corrugated roof sheets – Ground Floor (Room 14)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 37</b>	<b>Flash guards within fuse box – Ground Floor (Room 14)</b>	<b>Very Low</b>	<b>12 Monthly</b>	<b>03.10.26</b>
<b>Item 38</b>	<b>Corrugated roof sheets – Ground Floor (Room 16)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 39	No asbestos	Is present		
<b>Item 40</b>	<b>Corrugated wall sheets – Ground Floor (Room 16)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 41</b>	<b>Ceiling boards – Ground Floor (Room 18)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
<b>Item 42</b>	<b>Debris to floor – Ground Floor (Room 18)</b>	<b>Low</b>	<b>Do not</b>	<b>Inspect</b>
<b>Item 43</b>	<b>Flash guards within fuse box – Ground Floor (Room 18)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 44</b>	<b>Gasket to pipe flange – Ground Floor (Room 18)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 45</b>	<b>Ceiling boards – Ground Floor (Room 19)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
<b>Item 46</b>	<b>Debris to floor – Ground Floor (Room 19)</b>	<b>Low</b>	<b>Do not</b>	<b>Inspect</b>

<b>Item 47</b>	<b>Flash guards within fuse box – Ground Floor (Room 19)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 48</b>	<b>Gasket to pipe flange – Ground Floor (Room 19)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 49</b>	<b>Rope to floor – Ground Floor (Room 19)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 50	Ceiling boards – Ground Floor (Room 20)	Low	6 monthly	building demolished
Item 51	No asbestos	Is present		
Item 52	Damp proof course – Ground Floor (Room 20)	Very Low	12 monthly	building demolished
<b>Item 53</b>	<b>Ceiling boards – Ground Floor (Room 21)</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 54	No asbestos	Is present		
<b>Item 55</b>	<b>Gaskets to air pump – Ground Floor (Room 21)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
Item 56	No asbestos	Is present		
Item 57	No asbestos	Is present		
Item 58	No asbestos	Is present		
Item 59	No asbestos	Is present		
Item 60	No asbestos	Is present		
Item 61	No asbestos	Is present		
Item 62	No asbestos	Is present		
Item 63	No asbestos	Is present		
Item 64	No asbestos	Is present		
Item 65	No asbestos	Is present		
Item 66	No asbestos	Is present		
Item 67	No asbestos	Is present		
Item 68	No asbestos	Is present		
Item 69	No asbestos	Is present		
Item 70	No asbestos	Is present		
Item 71	No asbestos	Is present		

<b>Item 72</b>	<b>Corrugated roof/apex/cowl sheet to warehouse – External (warehouse 1)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 73</b>	<b>Corrugated roof/apex/cowl sheet to warehouse – External (warehouse 4)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 74</b>	<b>Corrugated sheet canopy – External (Warehouse 4)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 75</b>	<b>Guttering – External (Warehouse 4)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 76</b>	<b>Damp proof course – External (Warehouse 4)</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
Item 77	No asbestos	Is present		
<b>Item 78</b>	<b>Cement debris to ground – External</b>	<b>Very Low</b>	<b>Do not</b>	<b>Inspect - Item no longer there</b>
<b>Item 79</b>	<b>Cement Ceiling panels – Warehouse 2</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 80	No asbestos	Is present		
Item 81	No asbestos	Is present		
<b>Item 82</b>	<b>Ceiling panels – Warehouse 2</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 83	No asbestos	Is present		
Item 84	No asbestos	Is present		
Item 85	No asbestos	Is present		
Item 86	No asbestos	Is present		
<b>Item 87</b>	<b>Cement fascia – Warehouse 2 External</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
<b>Item 88</b>	<b>Ceiling cement panels – Warehouse 3</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>

<b>Item 89</b>	<b>Boxing – Warehouse 3</b>	<b>Medium</b>	<b>3 monthly</b>	<b>03.10.25</b>
<b>Item 90</b>	<b>Cement walls – Warehouse 3</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 91	No asbestos	Is present		
Item 92	No asbestos	Is present		
Item 93	No asbestos	Is present		
Item 94	No asbestos	Is present		
<b>Item 95</b>	<b>Canopy – Warehouse 3</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 96	No asbestos	Is present		
<b>Item 97</b>	<b>Cement Pipe - Warehouse 3</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 98	No asbestos	Is present		
Item 99	No asbestos	Is present		
Item 100	No asbestos	Is present		
<b>Item 101</b>	<b>Underside of roof Warehouse 4</b>	<b>Very Low</b>	<b>12 monthly</b>	<b>03.10.26</b>
<b>Item 102</b>	<b>Wall Cladding Warehouse 4</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>
Item 103	No asbestos	Is present		
Item 104	No asbestos	Is present		
<b>Item 105</b>	<b>Lining to fire door Warehouse 4</b>	<b>Low</b>	<b>6 monthly</b>	<b>03.04.26</b>



**Form 2****Periodic Return**

<b>Premises</b>	
<b>Date of Inspection</b>	
<b>Inspection By (signature)</b>	
<b>Print Name</b>	

**Good Practice Guidance:**

- Take photographs of ACMs for each inspection and store for future reference
- Compare previous photographs with current condition state to determine whether there has been any deterioration since the last inspection
- Replace missing/damaged asbestos labels/stickers

<u>Ref:</u>	<u>Condition</u>	<u>Action Required</u>	<u>Comments</u>
Same/change		Yes/No	

Sunderland  
City Council

**For Office Use Only**

<b>Actions Required</b>	
<b>Actions Completed</b>	
<b>Alterations to Register</b>	



**Sunderland  
City Council**